

Tolerance Table list(unit:mm), H is Positive Tolerance(+), h is Negative Tolerance (-)

Diameter	h6	h7	h8	h9	h10	h11	h12
<3	0.006	0.01	0.014	0.025	/	/	/
>3~6	0.008	0.012	0.018	0.03	0.048	0.075	0.12
>6~10	0.009	0.015	0.022	0.036	0.058	0.09	0.15
>10~18	0.011	0.018	0.027	0.043	0.07	0.11	0.18
>18~30	0.013	0.021	0.033	0.052	0.084	0.13	0.21
>30~50	0.016	0.025	0.039	0.062	0.1	0.16	0.25
>50~80	0.019	0.03	0.045	0.074	0.12	0.19	0.3